




When Good Blenders Go Bad... The Out of Warranty Repair Program!



McDantim, Inc. takes pride in manufacturing a reliable, accurate Blender that lasts for years beyond our warranty. All Beverage Line Models (TM-1, TM-1HF, TM-2 and TM-2HF) come with a Five Year Limited Warranty which covers out of specification gas blends and leaks. (Blenders filled with contaminants are not covered under our warranty.)

Here is our **Out of Warranty Repair Program**. These prices are not based on our distributor level pricing and are the same to end-users. Note: **McDantim** does its best at confirming ownership of the Blender before performing repairs.

Regulator assemblies are still available for purchase for both the old black plastic and white powder coated panels.

Tier 1 - Evaluation

Work Performed & Additional Benefits

1. Leak check.
2. Blend check.
3. Panel cleaned to best possible condition.
4. Panel relabeled.

90-day warranty.

Only for Beverage Line Models

\$73.50

Tier 2A - Blending Assembly Only Refurbishment

Work Performed & Additional Benefits

1. Leak check.
2. Blend check.
3. Blender Rebuild to current spec.
 - a. New EPDM Seals.
 - b. New 1/1 and B/R diaphragms.
 - c. New 1/1 and B/R caps.
 - d. New flow elements.
4. Retune to current spec.
5. Panel cleaned to best possible condition.
6. Panel relabeled.

1-year warranty.


TM-1 Single Blender
 TM-1HF Single High Flow Blender
 TM-2 Double Blender
 TM-2HF Double High Flow Blender

\$138.50

\$141.50

\$146.50

\$233.50



Tier 2B - Panel Assembly Replacement and/or Refurbishment of Selected Components

Work Performed & Additional Benefits

1. Leak check.
2. Blend check.
3. Panel Components Replaced to current spec.
 - a. New inlet regulators assemblies.
 - b. New outlet regulator assemblies.
 - c. New check valve outlet assemblies.
 - d. Ball valves cleaned to best possible condition.
 - e. New tubing.
 - f. New Panel.
4. Panel relabeled.

1-year warranty.

TM-1 Single Blender	\$199.00
TM-1HF Single High Flow Blender	\$199.00
TM-2 Double Blender	\$228.50
TM-2HF Double High Flow Blender	\$254.00

Tier 3 - Full Panel Replacement and Refurbishment

Work Performed & Additional Benefits

1. Includes all the part replacement and refurbishment listed in Tiers 2A and 2B.

2-year warranty.

TM-1 Single Blender	\$335.00
TM-1HF Single High Flow Blender	\$345.50
TM-2 Double Blender	\$375.00
TM-2HF Double High Flow Blender	\$448.00

Extended 3-Year Warranty

Only available on Tier 3 work.

Only for Beverage Line Models	\$90.50
-------------------------------	---------

Regulator Assemblies

Inlet Regulator Assembly (<i>specify minimum inlet psi</i>)	\$31.00
Black Panel Outlet Assembly (<i>specify which outlet</i>)	\$65.00
White Panel Outlet Assembly (<i>specify which outlet</i>)	\$38.00

Questions? Contact Sales by phone toll free at 888.735.5607 or email at orders@mcdantim.com